

Emergency Road Damage Assessment (ERDA) Resource Report

Date Exported: 3/18/2025 1:49 PM



SCORING VALUES AND WEIGHTS FOR THIS REPORT

Maximum Values:

Travel Volume = 10
Detour Time = 5
Loss of Lane = 5
Compromised Utilities/Culverts = 3
Access and Functional Needs = 10
Critical Facilities = 2

TOTAL MAXIMUM VALUE = 35

Normalized Maximum Values:

$35 \times .15 = (5.25)$ Travel Volume
 $35 \times .28 = (9.8)$ Detour Time
 $35 \times .25 = (8.75)$ Loss of Lane
 $35 \times .08 = (2.8)$ Compromised Utilities/Culverts
 $35 \times .12 = (4.2)$ Access and Functional Needs
 $35 \times .12 = (4.2)$ Critical Facilities

Normalized values converted to 1-100 scale

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
69.1	(8)	P42308	EUREKA CANYON RD	0.35	40 foot long slipout, 3 ft into road	2023
CAVA Variables	Critical Facilities: 12	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 5.33			FEMA Eligible: No	
65.9	(9)	NELSON RD	0.44	road washout due to clogged culvert/	2017	
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 8			FEMA Eligible: Yes	
62	(10)	P42567	REDWOOD LODGE RD	2.02	Road settlement from 2017 repair site	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 25	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
62	(12)	P42324	REDWOOD LODGE RD	1.80	Culvert/bridge failure	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 25	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
60.3	(10)	P42471	REDWOOD RD	??? 0.05		2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
59	(10)	P42581	UPPER EAST ZAYANTE	2.51		2023
CAVA Variables	Critical Facilities: 12	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
53.9	(5)	P42367	MOUNTAIN CHARLIE	1.66	45' long by 18' tall slipout 2' into	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 8			FEMA Eligible: Yes	
53	(8)	P42309	REDWOOD RD	1.08	36" culvert failure with sinkhole in	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
52.9	(9)		LOMPICO RD	0.80		2017
CAVA Variables	Critical Facilities: 12	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
52.9	(9)		LOMPICO RD	1.22		2017
CAVA Variables	Critical Facilities: 12	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
52.5	(6)	P42469	CATHEDRAL DR	0.85 at	15' long by 2-3' in	2023
CAVA Variables	Critical Facilities: 12	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
51.8	(8)		EUREKA CANYON RD	5.05		2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
51.8	(8)		EUREKA CANYON RD	4.67	Slipout	2017
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28	
County Variables	Loss of Lane: 10		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
51.8	(7)	P42501	EUREKA CANYON RD	3.55	Slipout 25x20 deep	2022-2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28	
County Variables	Loss of Lane: 10		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
51.7	(9)	P42442	UPPER EAST ZAYANTE	1.18	Road edge slipped out from clogged	2023
CAVA Variables	Critical Facilities: 12		Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 2.67		FEMA Eligible: No	
50.7	(11)	P24131	PAULSEN RD	0.93	Road edge damage. 60-100 ft	2023-2024
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 8.4	Detour Time: 5.6	
County Variables	Loss of Lane: 25		Compromised Utilities/Culverts: 2.67		FEMA Eligible: No	
49.5	(8)	P42425	EUREKA CANYON RD	6.76	Washout. Road edge and berm failure	2022-2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 2.67		FEMA Eligible: No	
49	(8)		UPPER EAST ZAYANTE	1.68	slipout - 45' LONG X 10' D - soldier pile	2017
CAVA Variables	Critical Facilities: 12		Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 0		FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
48.6	(6)	P42363	MOUNTAIN CHARLIE	1.94	50' long by 15' tall slipout near culvert	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
48.3	(6)	P24130	MOUNTAIN VIEW RD	0.25	Shoulder of the road is cracking, slipping	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 3.6	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
48.2	(5)	P24123	SKYVIEW TE	1.40	Sinkhole near 15" culvert. Sinkhole 11'	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
47.9	(6)	P42387	NELSON RD	0.41	Slipout between two previous sites	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
47.9	(8)	P42568	RIDER RD	0.85	30' slipout - rock infill	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
46.8	(9)		EUREKA CANYON RD	3.36	Major slipout (30') with signs of potential	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
46.8	(8)		EUREKA CANYON RD	5.33	Slipout embankment shoulder adjacent to	2017
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
46.8	(8)		EUREKA CANYON RD	8.39	Slipout - 50' wide x 20' deep	2017
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
46.2	(5)	P42480	MOUNTAIN CHARLIE	1.89	10' wide x 30' deep	2022-2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 5.33		FEMA Eligible: Yes	
46.2	(5)	P24135	MOUNTAIN CHARLIE	4.99	Small washout, 5'x5'x5'	2023-2024
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 5.33		FEMA Eligible: Yes	
45.9	(5)	P42437	MOUNTAIN CHARLIE	2.55	15' long by 10' deep shoulder slipout	2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: Yes	
45.9	(1)	P42411	MOUNTAIN CHARLIE	4.75		2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: Yes	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
45.3	(8)	P42320	REDWOOD RD	0.97	10' long by 7' tall shoulder slipout	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
45	(12)	P42303	CHINA GRADE RD	0.62	Culvert washout, road gone for 50'	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5,6		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 8			FEMA Eligible: No	
45	(1)	P42433	HAZEL DELL RD	2.35	Slipout 15' long by lane	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 11.2		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
44.7	(9)	P42481	BEAR CREEK RD	7.41	Road Edge slipped out 30' long	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
44.5	(7)		EUREKA CANYON RD	3.16	Failure of 3' culvert and associated	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
44.5	(7)	P42359	HIGHLAND WY	2.88	Road edge damage on inboard side	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
43.6	(4)	P24120	RIVA RIDGE RD	0.10	Sinkhole on road edge 2'x6' deep	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
43.2	(7)	P42552	VIENNA DR	0.48 @	6' wide x 8' deep shoulder (asphalt)	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 5.33			FEMA Eligible: Yes	
43.2	(7)	P24118	VIENNA DR	0.49	Slipout at walkway edge 35'x 20'	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 5.33			FEMA Eligible: Yes	
43	(1)	P76844	GAFFEY RD	0.08	Sink hole found, radio info at this point.	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
42.9	(8)	P42569	RIDER RD	1.38		2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
42.9	(9)	P45269	RIDER RD	0.61	Slipout, 2 sites: one 26'x10'x10' - other	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
42.9	(7)	P42570	RIDER RD	0.67	Slipout, 63' x 15' tall x 15' wide	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
42.9	(8)	P24119	PORTER GULCH RD	0.51	Road undermining at creek. 70-90' long	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
42.9	(7)	P24121	RIDER RD	0.77	Road edge damage near ditch line	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
42	(1)		BEAR CREEK RD	5.68		2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
42	(9)	P24128	BEAR CREEK RD	6.73	Road edge slipout 30' x 60'	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
41.8	(7)	P42423	EUREKA CANYON RD	5.09	10' edge slipout	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
41.8	(7)	P42535	EUREKA CANYON RD	5.17		2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
41.8	(10)	P42337	HIGHLAND WY	0.70	30' long by 5' tall shoulder slipout 6' into	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
41.7	(6)	P42344	BEACH DR	RIO DEL	Damaged hand railing, curb, stairs and	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 1.2	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
41.4	(9)	P24134	MOUNT BACHE RD	0.11	Road sinking for approx 40-50'.	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 11.2		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
40.8	(8)	P42374	REDWOOD LODGE RD	2.25	Shoulder damage, 30' long, 2' into	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 16.8		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
40.8	(11)	P42457	STETSON RD	0.18	Crib wall failure road undermined	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 25	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
40.6	(7)	P42562	MOUNTAIN VIEW RD	0.49		2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 3.6	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
40.5	(9)	P42529	LODGE RD	1.10	60 x 50 slipout. Only 5' left of road	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 25	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
40.5	(7)	P24115	SPANISH RANCH RD	0.63	Road edge erosion, still need to	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
39.7	(9)	P42430	BEAR CREEK RD	2.39	Collapsed culvert. Possibly smashed by	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
39.7	(10)	P42431	BEAR CREEK RD	4.18	Collapsed culvert. Deformed from	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
38.9	(7)	P42321	CASSERLY RD	0.72	Slip out. 15x10	2022-2023
CAVA Variables	Critical Facilities: 12	Travel Volume: 9	Access and Functional Needs: 9.6	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
38.2	(8)	P42452	REDWOOD DR (SC)	1.67	failed 36" CMP pipe plugged caused	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
37.9	(8)	P42518	LITTLE BASIN RD	1.50	road edge slipout towards creek 30'x12'	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
37.9	(7)	P42458	VIENNA DR	0.30	Shoulder of road collapsed	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 28		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
37	(8)	P24109	EAST ZAYANTE RD	1.01	Slipout 20' x 40'	2023-2024
CAVA Variables	Critical Facilities: 12	Travel Volume: 12	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
35.5	(9)		SWANTON RD	3.00	60' L slipout, install pier/lagging wall,	2017
CAVA Variables	Critical Facilities: 12	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
34.8	(6)		BROWNS VALLEY RD	2.93	Minor slipout on edge of roadway	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 4.8	Detour Time: 16.8		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
34.6	(5)	P42537	TROUT GULCH RD	1.53	40' long x 20' deep shoulder slipout	2022-2023
CAVA Variables	Critical Facilities: 12	Travel Volume: 12	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
34.6	(5)	P24106	TROUT GULCH RD	1.31	Slope erosion from falling tree	2023-2024
CAVA Variables	Critical Facilities: 12	Travel Volume: 12	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
34.3	(8)	P42355	BEAN CREEK RD	1.87	Roadway Slipout, 50' long x 20' tall, Tree	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 1.2	Detour Time: 5.6		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
34.3	(8)	P24108	SUMMIT RD	2.12	Road edge failing at culvert inlet	2023-2024
CAVA Variables	Critical Facilities: 12	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
33.1	(8)	P24110	MORRELL RD	0.85	Slipout at creek affecting the road. Road	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 20	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
32.2	(5)		CASSERLY RD	2.93	Slipout - 80'Lx10'D - Install soldier pile	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 12	Access and Functional Needs: 9.6	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
32.1	(8)	P42433	GREEN VALLEY RD	2.34	25' long x 15' deep slipout. Edge of road	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
32	(8)	GLENWOOD CUTOFF	0.02	35' long slipout, install cribwall, new	2017	
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
32	(10)	NORTH RODEO GULCH	3.82	Slipout	2017	
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
32	(9)	P42546	NORTH RODEO GULCH	3.77	Road edge washout near existing crib	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
32	(9)	P24116	NORTH RODEO GULCH	1.88	Tree fall damaged 1/4 of the road edge	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
31.9	(7)	P24114	EL RANCHO DR	1.64	Large void near culvert, temporary	2023-2024
CAVA Variables	Critical Facilities: 12	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 5.33			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
30.8	(5)	P42526	LODGE RD	0.50	40x100 slip out	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 5.33				FEMA Eligible: Yes
30.8	(6)	P42494	LAUREL RD	1.10 AT	Road edge damage from tree fall	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 16.8		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0				FEMA Eligible: No
29.9	(5)		CASSERLY RD	3.39	Slipout - 20'Wx15'D	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 12	Access and Functional Needs: 9.6	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67				FEMA Eligible: No
29.7	(5)	P42464	GREEN VALLEY RD	0.02	Road edge failing	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 5.33				FEMA Eligible: Yes
29.4	(4)	P42453	WEBB RD	1.30	Damage around culvert, need to	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 3.6	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 2.67				FEMA Eligible: Yes
28.1	(5)		MILLER CUTOFF RD	0.49	slipout next to existing cribwall	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0				FEMA Eligible: Yes

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
28.1	(5)	P42445	SCHULTIES RD	??? 0.85	1/4 of the road dropped 10 inches	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 15	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
27.7	(5)	P42504	MANFRE RD	0.51 AT	Road edge damage 20'x1'	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 9.6	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
27	(1)	P42555	NORTH RODEO GULCH	1.13		2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
27	(8)	P24136	NORTH RODEO GULCH	2.70	3 sections of road edge damage. 15x4,	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
26.7	(7)	JARVIS RD	0.64	slipout		2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 3.6	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
26.5	(6)	P42502	SPRECKELS DR	0 (AT)	Road edge slipout	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 13.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
25	(8)		SMITH GRADE	4.06	12' L slipout, install pier and lagging	2017
CAVA Variables	Critical Facilities: 0		Travel Volume: 12	Access and Functional Needs: 2.4	Detour Time: 5.6	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
25	(6)	P42428	HAZEL DELL RD	2.57	Slipout 50' long	2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 11.2	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
25	(6)	P42426	HAZEL DELL RD	2.69 Above	Slipout 25'	2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 11.2	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
25	(6)	P42427	HAZEL DELL RD	2.64	Slipout	2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 11.2	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 0		FEMA Eligible: No	
25	(6)	P42414	PAUL SWEET RD	1.00	Fallen oak tree, pavement damage	2022-2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 12	Access and Functional Needs: 2.4	Detour Time: 5.6	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: Yes	
25	(6)	P24138	HAZEL DELL RD	3.34	Road damage 6'x6'	2023-2024
CAVA Variables	Critical Facilities: 0		Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 11.2	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 0		FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
24.7	(8)	P42516	ICE CREAM GRADE	1.24	Road Edge failure above culvert wall	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
24.3	(6)	P42380	BEAN CREEK RD	1.05	40' long slipout along creek bank, 2' into	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 1.2	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
23.8	(9)	P42350	VALENCIA RD	0.25	Large slipout from above. Road damage	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
23.8	(5)	P42542	COX RD	1.97	Slipout, 60' long	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
23.1	(7)		KINGS CREEK RD	3.03	18' L slipout, install soldier pile wall,	2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
23.1	(5)	P42479	TROUT GULCH RD	3.50	tree fell, 25' long washout	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
23.1	(6)	P42539	TROUT GULCH RD	3.44		2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 10	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
22	(1)	P42575	NORTH RODEO GULCH	3.72	Damage from stream flow	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
22	(8)	P24132	NORTH RODEO GULCH	2.58	Tree fell away from road and caused	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: No	
21.7	(7)	JARVIS RD	0.68	slipout		2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 3.6	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
21.7	(7)	JARVIS RD	1.02, 1.04,	slipout		2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 3.6	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
21.2	(6)	GLENWOOD DR	2.02	Slope failure below existing pile wall		2017
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
21.1	(6)	P24107	DAY VALLEY RD	1.18	Wash out 25' x 10'.	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 10.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
20.5	(5)	P42527	LODGE RD	0.70	40x100 slip out	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
20.5	(5)	P42528	LODGE RD	1.00	30x100 slip out	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
20.5	(5)	P24112	LODGE RD	0.55	Slip out	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
20.5	(5)	P24111	LODGE RD	0.57	Slip out	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 2.4	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
19.4	(5)	P42463	GREEN VALLEY RD	0.01	Road Failing	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 4.8	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
18.8	(8)	P42444	GLEN CANYON RD	0.39	Sink Hole found near culvert inlet	2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 0	Detour Time: 5.6	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 2.67		FEMA Eligible: No	
18.8	(6)	P42532	DAY VALLEY RD	0.95	Sink in the road, rotted culvert	2022-2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 0	Detour Time: 5.6	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 2.67		FEMA Eligible: No	
18.8	(8)	P24122	BRANCIFORTE DR	1.64	Sinkhole near culvert. 2x2x2	2023-2024
CAVA Variables	Critical Facilities: 0		Travel Volume: 10.5	Access and Functional Needs: 0	Detour Time: 5.6	
County Variables	Loss of Lane: 0		Compromised Utilities/Culverts: 2.67		FEMA Eligible: No	
18.1	(4)	P42373	GEOFFROY DR	0.21	Shoulder damage	2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: Yes	
18.1	(4)	P42538	TROUT GULCH RD	2.44		2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: Yes	
18.1	(5)	P42550	SCHULTIES RD	1.96	30' slipout - road undermined - 15' deep	2022-2023
CAVA Variables	Critical Facilities: 0		Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6	
County Variables	Loss of Lane: 5		Compromised Utilities/Culverts: 0		FEMA Eligible: Yes	

Final Score	(Old DPW Score)	CAMS #	Road	Location	Description	Storm Year
18.1	(7)	P42478	TROUT GULCH RD	3.09	Road edge slip out, 70' long	2022-2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
18.1	(7)	P24125	KINGS CREEK RD	3.26	Road edge damage from tree uproot	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
18.1	(6)	P24137	SCHULTIES RD	0.23	Deformation of the road, cracking and	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 5	Compromised Utilities/Culverts: 0			FEMA Eligible: Yes	
17.3	(7)	P24133	GRANITE CREEK RD	0.82	Road edge damage 4'x11'	2023-2024
CAVA Variables	Critical Facilities: 0	Travel Volume: 9	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: No	
15.8	(1)	P42489	GEOFFROY DR	0.14 at	Shoulder damage	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	
15.8	(5)	P42549	SCHULTIES RD	0.44	corroded 12" cmp - slipout 25'	2023
CAVA Variables	Critical Facilities: 0	Travel Volume: 7.5	Access and Functional Needs: 0	Detour Time: 5.6		
County Variables	Loss of Lane: 0	Compromised Utilities/Culverts: 2.67			FEMA Eligible: Yes	

